

North America Emission Control Area Fuel Oil Non-Availability Report

ECA0100

1

2

##

##(Include Double Pound for comments, not form fields)

##Report Form ID

Ship Operator Name

WALLEM SHIOMENAGEMENT LIMITED HK

3

4

5

6

7

Vessel Name	Flag Country	IMO ID Number	Date of ECA First Notice	Location of ECA First Notice
BIANCO VENTURE	PANAMA	9278739	18-Jul-13	46-16.8N, 048-11.4W

8

9

10

Name of Ports after First Notice	Name of Last Port before ECA Entry	Name of Port with Fuel Oil Supply Disruption
CHARLESTON, SC	CHARLESTON,SC	OFF SKAW. DENMARK

Name of Original Fuel Supplier with Disruption	Number of Fuel Suppliers Contacted
STENA OIL AB, SWEDEN	TEL: +46 10-445-1410 , EMAIL: bunkers@stenaoil.com

13

14

15

Date of Entry in the ECA	Time of Entry in the ECA	Sulfur Content of Non-Compliant Fuel Oil
18-Jul-13	1700LT	2.10%

16

17

18

Projected Hours on Main Propulsion	Name of First POC	Compliance Fuel Oil Available at First POC?
55 HRS	HOUSTON	YES

Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC
YES	TWO

21

22

23

Name of Second POC	Compliant Fuel Oil at Second POC?	Plan to Bunker Compliance Fuel Oil at Second POC?
TWO	YES	YES

24

25

26

Number of Fuel Suppliers Contacted at the Second POC?	Date of Exit from ECA?	Time of Exit from ECA?
TWO	ABT 15TH-AUG-2013	2000LT

ED_002238_00003693-00010

Number of Ports visited in the ECA

ROTTERDAM,,/NETHERLAND. HALMSTAD, MALMO/SWEDEN, CHARLESTON/SC/USA

30

31

32

Previously submitted ECA0100 forms?	Number of Submitted Reports	Designated Corporate Official Name
NO	NO.1	J.LAURITZEN (USA),INC

Designated Corporate Official E-mail	Designated Corporate Official Phone Number
<u>operation@lauritzenbulk.com</u>	mob: +1 203 434 6394

Description of Actions to Achieve Compliance
will supply the LSIFO before loading berth.